

Facility Name: Utica Resource Operating, LLC -- Detweiler Well Pad

Facility Location: 39.988577, -81.386899, Salesville, Ohio

Date of Inspection: April 18, 2019

APPENDIX A: DIGITAL IMAGE LOG

1. Inspector Name: Natalie Topinka	2. Date(s) of Inspection: April 18, 2019
3. Company/Facility Name: Utica Resource Operating, LLC -- Detweiler Well Pad	4. Street Address, City, State: 39.988577, -81.386899, Salesville, Ohio
5. Number of Images: 22	6. Archival Record Location: CD-R labeled "Utica Resource Operating, LLC -- Detweiler well pad -- Inspection photos 4/18/19"

Image Number	File Name	Date and time	Latitude and Longitude	Description of Image
1	P4180019.JPG	4/18/2019 10:15 EDT	40.043056, -81.382778	Thief hatch with condensate droplets & staining
2	P4180020.JPG	4/18/2019 10:15 EDT	40.043056, -81.382778	Thief hatch with condensate droplets, paraffin build-up, & staining
3	P4180021.JPG	4/18/2019 10:19 EDT	39.989167, -81.386667	Thief hatch with condensate droplets, paraffin build-up, & staining
4	P4180022.JPG	4/18/2019 10:23 EDT	39.989398, -81.386673	Thief hatch with condensate droplets
5	MOV_2334.mp4	4/18/2019		Emissions from thief hatches viewed from ground level
6	MOV_2335.mp4	4/18/2019		Emissions from thief hatch
7	MOV_2336.mp4	4/18/2019		Emissions from thief hatch
8	MOV_2337.mp4	4/18/2019		Emissions from thief hatch
9	MOV_2338.mp4	4/18/2019		Emissions from thief hatch

Facility Name: Utica Resource Operating, LLC – Detweiler Well Pad
Facility Location: 39.988577, -81.386899, Salesville, Ohio
Date of Inspection: April 18, 2019

10	MOV_2339.mp4	4/18/2019	Emissions from thief hatch
11	MOV_2340.mp4	4/18/2019	Emissions from thief hatch
12	MOV_2341.mp4	4/18/2019	Emissions from thief hatch
13	MOV_2342.mp4	4/18/2019	Emissions from thief hatch
14	MOV_2343.mp4	4/18/2019	Emissions from thief hatch
15	MOV_2344.mp4	4/18/2019	Emissions from LP separator #1 enclosure vent
16	MOV_2345.mp4	4/18/2019	Emissions from temperature controller inside LP separator #1 enclosure
17	MOV_2346.mp4	4/18/2019	Emissions from other controllers inside LP separator #1 enclosure
18	MOV_2347.mp4	4/18/2019	Combustor stack
19	MOV_2348.mp4	4/18/2019	Emissions from LP separator #2 enclosure vent
20	MOV_2349.mp4	4/18/2019	Emissions from piping at LP separator #2 enclosure
21	MOV_2350.mp4	4/18/2019	Intermittent emissions from 4/18/2019LP separator #2 enclosure vent
22	MOV_2351.mp4	4/18/2019	Emissions from leak point in LP separator #2 enclosure